

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	978	(electronic same engine same control\$4)and (electronic same transmission same control\$4)and (signal same transmission same link\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:37
L2	84	(signal near4 transmission near5 link\$4) same (malfunction\$4 or abnormal or defect\$4 or impairment)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:40
L3	1	1 and 2	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:40
L4	1	(electronic near engine near4 control\$4) same (electronic near4 transmission near5 control\$4) same (function\$4 same (impairment or abnormal or malfunction or defect\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:43
L5	24	(electronic near engine near4 control\$4) same (function\$4 same (impairment or abnormal or malfunction or defect\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:43
L6	151	limit\$4 same maximum same permissible same (engine near4 torque)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:44

L7	1932	((electronic same engine same control \$4)or (electronic same transmission same control\$4)) same function\$4 same (impairment or abnormal or malfunction\$4 or defect\$4 or fail\$4 or fault)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:46
L8	4	6 and 7	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:46
L9	5	("5204816"   "5233530"   "5247444"   "5999875"   "6067498").PN. OR ("6205394").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/01/20 16:47
L10	44	((electronic near engine near4 control \$4)or (electronic near4 transmission near5 control\$4)) same (function\$4 same (impairment or abnormal or malfunction or defect\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:50
L11	2	6 and 10	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:50
L12	6925	((electronic same engine same control \$4)or (electronic same transmission same control\$4)) same (impairment or abnormal or malfunction\$4 or fault or fail\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:53

L13	7	6 and 12	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:53
L14	1748	(( engine near4 control\$4) or ( transmission near5 control\$4)) same (function\$4 same (impairment or abnormal or malfunction or defect\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:58
L15	5	6 and 14	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 16:58
L16	285	maximum same permissible same (engine near4 torque)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 17:01
L17	10	16 and 14	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 17:01
L18	23	("4166440"   "4403527"   "4724723"   "4889014"   "4933851"   "4938100"   "4939956").PN. OR ("5103692").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/01/20 17:06
L19	176598	"701"/\$.ccls. or "123"/\$.ccls. or "477"/\$.ccls. or "180"/\$.ccls.	USPAT	OR	OFF	2009/01/20 17:09
L20	49	6 and 19	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 17:09

L21	1456	19 and 12	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 17:09
L22	4	6 and 21	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/01/20 17:10

1/20/09 5:11:07 PM

C:\ Documents and Settings\dtran2\My Documents\EAST\Workspaces\5231862.wsp